

C14 Design Sp. z o.o., 60-175 Poznań

Dear CWT International,

I am writing to you today to confirm the successful installation of the Vulcan 3000 unit in McDonald's, Poland. Our clients were having trouble with hard scale deposits forming on the hot water heater, which was decreasing efficiency and raising heating costs.

We installed the Vulcan 3000 unit and after only a few days the existing scale deposits on the heating element began to break down significantly. After 3 months they had been completely removed and there was no sign of new deposits forming.

Please see the below photos which confirm these results.

Regards

*Jakub Gliszczyński*



Installation of the Vulcan unit



Scale deposits breaking down after only a few days



Scale deposits completely removed after 3 months