

The Cooling Systems in the Poultry Farm



Installation details

Location: 3 chicken farms in Morocco

Area:

- 6 cooling systems
- Drinking water of hens


Model:  S10

Result: The customer built the new cooling tower pads to test the Vulcan effects and compared the old pads which had not been cleaned for more than 5 years.

After Vulcan had been installed for 2 weeks:

- For the new pads, the new scale formed like powder, and it can be eliminated very easily.
- For the old pads, it took longer time to clean the old scale with a water gun.

Installed by: STE ETCT INDUSTRIE



Vulcan S10 was installed in the water main to treat 6 cooling systems in 3 chicken farms.



Without any water treatment, the scale was hard like stones, which had not been cleaned for more than 5 years.



After Vulcan S10 had been installed for 2 weeks, the old scale had been softer, and the new scale had formed as powder. The new scale was easy to clean, and the old scale took more time to clean up with a water gun.

See the video here: www.bit.ly/ma-poultry